Errata

NFPA 70®

National Electrical Code®

2026 Edition—Print Only

Reference: Table 430.22(H)
Errata No: 70-26-4 Print Only

The Code-Making Panel 11 and National Electrical Code Correlating Committee note the following error in the 2026 edition of *NFPA 70®*, *National Electrical Code®.*

1. Table 430.22(H) was inadvertently omitted from the print copy of the NEC and should read as follows:

Table 430.22(H) Conductor Short Circuit Factors (F_c)

F_c	Conductor	T_1	T_2
0.0662	Copper thermoset insulated conductors	75°C	200°C
0.0614	Copper thermoset insulated conductors	90°C	200°C
0.0587	Copper thermoplastic insulated conductors	60°C	150°C
0.0529	Copper thermoplastic insulated conductors	75°C	150°C
0.0468	Copper thermoplastic insulated conductors	90°C	150°C
0.0433	Aluminum thermoset insulated conductors	75°C	200°C
0.0402	Aluminum thermoset insulated conductors	90°C	200°C
0.0384	Aluminum thermoplastic insulated conductors	60°C	150°C
0.0346	Aluminum thermoplastic insulated conductors	75°C	150°C
0.0306	Aluminum thermoplastic insulated conductors	90°C	150°C

Issue Date: October 31, 2025

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/docinfo)

Copyright © 2025 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION