Producto Electric Corp.
11 Kings Highway, Orangeburg, NY 10962-1897
Tel: (845) 359-4900 Fax: (845) 359-4978
E-mail: info@pecoelect.com Web site: www.pecoelect.com

Split Bolt Service Connectors

Check up to five results to perform an action.



larger image

Results 1 - 17 of 17 **1**

Item #	Item Name	Material	Size	Std.Pkg.	Std. Pkg. Wt.	Dim. A	Dim. B	Note/Remark
SB-10	Split Bolt Service Connectors	Silicone Bronze	16-10 Str.	100	2	.71	.50	-
SB-8	Split Bolt Service Connectors	Silicone Bronze	12 Sol.-8 Str.	100	3	.99	.68	-
SB-6	Split Bolt Service Connectors	Silicone Bronze	10 Sol.-6 Sol.	100	5	1.12	.70	-
SBL-6	Split Bolt Service Connectors	Silicone Bronze	10 Sol.-6 Sol.	100	5	1.12	.70	* Holds 3 Wires Instead of 2 Wires
SB-4	Split Bolt Service Connectors	Silicone Bronze	8 Sol.-4 Sol.	100	8	1.27	.76	-
SBL-4	Split Bolt Service Connectors	Silicone Bronze	8 Sol.-4 Sol.	100	8	1.27	.76	* Holds 3 Wires Instead of 2 Wires
SB-3	Split Bolt Service Connectors	Silicone Bronze	6 Sol.-2 Sol.	100	11	1.42	.85	-
SB-2	Split Bolt Service Connectors	Silicone Bronze	6 Sol.-2 Str.	100	12	1.55	.92	-
SBL-2	Split Bolt Service Connectors	Silicone Bronze	6 Sol.-2 Str.	100	12	1.55	.92	* Holds 3 Wires Instead of 2 Wires
SB-1/0	Split Bolt Service Connectors	Silicone Bronze	4 Sol.-1/0 Str.	50	9	1.62	.98	-

SB-2/0	Split Bolt Service Connectors	Silicone Bronze	2 Sol.-2/0 Str.	25	8	1.74	1.13	-
SB-3/0	Split Bolt Service Connectors	Silicone Bronze	2 Sol.-3/0 Str.	25	10	1.97	1.28	-
SB-4/0-250	Split Bolt Service Connectors	Silicone Bronze	1/0 Sol.-250 MCM	25	13	2.37	1.49	-
SB-350	Split Bolt Service Connectors	Silicone Bronze	4/0 Str.-350 MCM	12	11	2.64	1.82	-
SB-500	Split Bolt Service Connectors	Silicone Bronze	250-500 MCM	12	16	3.19	2.37	-
SB-750	Split Bolt Service Connectors	Silicone Bronze	350-750 MCM	6	12	3.66	2.61	-
SB-1000	Split Bolt Service Connectors	Silicone Bronze	500-1000 MCM	6	17	4.01	2.82	-

Results 1 - 17 of 17 **1**

Print Back